

Oil Field Environmental Incident Summary

Incident: 20160309143004 **Date/Time of Notice:** 03/09/2016 14:30

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PARSHALL 47-2226H

Field Name: PARSHALL

Well File #: 27158

Date Incident: 3/8/2016 **Time Incident:** 15:30

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 90

Sec: 22

Qtr:

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 4 | Barrels | 4 | Barrels | 4 | barrels |

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/16/2016

Clean Up Concluded: 3/10/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Everything was tightened up and rechecked, the oil inside lined containment was removed with a vac truck. A hot oiler will flush and wash the rock with fresh water in the lined containment and while the vac truck removes the liquids.

Wastes Disposal Location: SWD

Agencies Involved: MHA & TAT

Updates

Date: 3/9/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained within diking according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA and EPA.